



JOE RUBIN 43099 CUMMINS/ONAN G200782095 - GENSET

Sample No: VPA045950

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
		VD4045050	VDA022102	
Sample Number		VPA045950	VPA032182 01 Feb 2022	
Sample Date		28 Jun 2023		
Machine Hours		373	148	
Oil Hours		0	0	
Oil Changed		Not Changd	Changed	
Sample Status		ATTENTION	ATTENTION	
OIL CONDITION				
Visc @ 100°C	cSt	<u> </u>	1 0.9	
Base Number (BN)	mg KOH/g	■8.5	□9.5	
Oxidation (PA)	%	57	40	
CONTAMINATION				
	0/	=0.1	=0.1	
Soot %	%	■ 0.1	0.1	
Nitration (PA)	%	47	41	
Sulfation (PA)	%	51	44	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	1.7	
Silicon	ppm	9	1 2	
Sodium	ppm	2	■3	
Potassium	ppm	■0	<u> </u>	
WEAR METALS				
Iron	ppm	□ 7	6	
Copper	ppm	■3	1 4	
Lead	ppm	■0	□ <1	
Tin	ppm	■ <1	<1	
Aluminum	ppm	■3	1 2	
Chromium	ppm	<1	1 <1	
Molybdenum		71	105	
Nickel	ppm	■ 7 1 ■ 0	105	
Titanium	ppm	_	0	
	ppm	■ <1		
Silver	ppm	0	<1	
Manganese	ppm		<1	
Vanadium	ppm	0	0	
ADDITIDDA				
Calcium	ppm	1386	2450	
Magnesium	ppm	746	217	
Zinc	ppm	1177	■1126	
Phosphorus	ppm	■ 952	□1034	
Barium	ppm	■ <1	□0	
Boron	ppm	4	97	
	I- P			

COASTAL CAROLINA YACHT SALES

145 LOCKWOOD BLVD CHARLESTON, SC US 29403 Contact: STEVE VASAS steve@ccyachtsales.com T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VP568144Unique No:10549117Signed:Don BaldridgeReport Date:11 Jul 2023

OIL ANALYSIS REPORT



