



MIKE VELYS ONAN C190527131 - GENSET

Sample No: VPA043911

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA043911	VPA039604	
Sample Date		29 Jun 2023	02 Nov 2021	
Machine Hours		299	207	
Oil Hours		299	207	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CONDITION				
Visc @ 100°C	cSt	13.8	13.8	
Base Number (BN)	mg KOH/g	■8.6		
Oxidation (PA)	%	68	65	
CONTAMINATION				
	0/		504	
Soot %	%	0.1	0.1	
Nitration (PA)	%	55	53	
Sulfation (PA)	%	56	54	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	<1.0	
Silicon	ppm	6	8	
Sodium	ppm	■ <1	3	
Potassium	ppm	□ 7	<u> </u>	
WEAR METALS				
Iron	ppm	4	4	
Copper	ppm	<u> </u>	4	
Lead	ppm	■0	<1	
Tin	ppm	<1	<1	
Aluminum	ppm	2	2	
Chromium	ppm	■ <1	- <1	
Molybdenum	ppm	1 5	5 2	
Nickel	ppm	■<1	- <1	
Titanium	ppm	<1	<1	
Silver	ppm	■ 0	<1	
Manganese	ppm		< 1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	2073	□ 1844	
Magnesium	ppm	117	432	
Zinc	ppm	■ 1135	1172	
Phosphorus	ppm	985	1025	
Barium	ppm	■0	0	
Boron	ppm	174	1 02	
	I I I			

Larry`s Lighthouse Marina

1250

AQUEBOGUE, NY US 11931

Contact: MAX FUHLBRUGGE info@lighthousemarina.com

T: x: F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP610438Unique No:10561113Signed:Don BaldridgeReport Date:18 Jul 2023

OIL ANALYSIS REPORT



