



## GEORGE ANDERSON DANIEL/502107 VOLVO PENTA 2203202348 - STERNDRIVE - CENTER GEARBOX

Sample No: VPA055885

**Oil Type:** VOLVO PENTA GL-5 SAE 75W140

SAMDLE INFORM	IATION			
SAMPLE INFORM	IATIUN			
Sample Number		VPA055885	 	
Sample Date		13 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>119</b>	 	
CONTAMINATION	N			
Water	%	<b>5.29</b>	 	
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	■10	 	
Potassium	ppm	<b>■</b> <1	 	
WEAD METALS				
WEAR METALS				
PQ		■30	 	
Iron	ppm	<u> </u>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<u> 11</u>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>4</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<u> </u>	 	
Magnesium	ppm	<u>^</u> 5	 	
Zinc	ppm	<b>■25</b>	 	
Phosphorus	ppm	■1320	 	
Barium	ppm	■2	 	
Boron	ppm	<b>225</b>	 	

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:VP794951Unique No:10603645Signed:Don BaldridgeReport Date:15 Aug 2023

## **OIL ANALYSIS REPORT**



