



## MICHAEL MURPHY DANIEL/502118 VOLVO PENTA 4012184962 - STERNDRIVE - GEARBOX

Sample No: VPA036833

**Oil Type:** VOLVO PENTA GL-5 SAE 75W140

SAMPLE INFORM	ΙΔΤΙΩΝ			
	INTION			
Sample Number		VPA036833	 	
Sample Date		25 Jul 2023	 	
Machine Hours		527	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>119</b>	 	
CONTAMINATION	N			
Water	%	<b>△</b> 0.500	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	■0	 	
Potassium	ppm	<b>■&lt;1</b>	 	
	ppin			
WEAR METALS				
PQ		<b>28</b>	 	
Iron	ppm	<b>756</b>	 	
Copper	ppm	<b>■</b> 3	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	■0	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<b>7</b>	 	
Molybdenum	ppm	<b>■&lt;1</b>	 	
Nickel	ppm	<b>■</b> 9	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■8</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>■</b> 34	 	
Magnesium	ppm	<b>2</b>	 	
Zinc	ppm	■24	 	
Phosphorus	ppm	<b>1303</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	■300	 	
	-  - · · ·			

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a moderate concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:VP794951Unique No:10603648Signed:Doug BogartReport Date:15 Aug 2023

## **OIL ANALYSIS REPORT**



