



ONAN H070089400 - GENSET

Sample No: VPA056814
Oil Type: NOT GIVEN

SAMPLE INFORMATION					
Sample Number		VPA056814			
Sample Date		08 Aug 2023			
Machine Hours		595			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 100°C	cSt	13.57			
Oxidation (PA)	%	55			
CONTAMINATION					
Soot %	%	□ 0.1			
Nitration (PA)	%	43			
Sulfation (PA)	%	49			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	7			
Sodium	ppm	■ 0			
Potassium	ppm	2			
WEAR METALS					
Iron	ppm	2			
Copper	ppm	1			
Lead	ppm	1			
Tin	ppm	■0			
Aluminum	ppm	■<1			
Chromium	ppm	■ 0			
Molybdenum	ppm	54			
Nickel	ppm	■0			
Titanium	ppm	0			
Silver	ppm	■<1			
Manganese	ppm	0			
Vanadium	ppm	0			
ADDITIVES					
Calcium	ppm	1205			
Magnesium	ppm	837			
Zinc	ppm	1218			
Phosphorus	ppm	1019			
Barium	ppm	2			
Boron	ppm	23			

JON DIESEL LLC

4915 241ST E MYAKKA CITY, FL US 34251 Contact: Jon Marquette jondieselllc@gmail.com T: (941)780-1330 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VPJONMYAUnique No:10603825Signed:Doug BogartReport Date:14 Aug 2023

OIL ANALYSIS REPORT



