



## DIANA PHILLIPS ONAN J860847540 - GENSET

Sample No: VPA056791

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA056791	 	
Sample Date		28 Aug 2023	 	
Machine Hours		701		
Oil Hours		0		
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>12.8</b>	 	
Base Number (BN)	mg KOH/g	■9.8	 	
Oxidation (PA)	%	54	 	
CONTAMINATION				
	0/			
Soot %	%	<b>0.1</b>	 	
Nitration (PA)	%	40	 	
Sulfation (PA)	%	49	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■</b> 3	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>■</b> <1	 	
WEAR METALS				
Iron	ppm	<b>5</b>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	 <1	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>  &lt;1</b>	 	
Molybdenum		<b>■58</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
	ppm	_		
Manganese Vanadium	ppm	<b>□</b> 0 0	 	
	ppm	U	 	
ADDITIVES				
Calcium	ppm	<b>1195</b>	 	
Magnesium	ppm	<b>733</b>	 	
Zinc	ppm	<b>1096</b>	 	
Phosphorus	ppm	<b>924</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>1</b>	 	
		_		

## **YACHT BASIN MARINA**

1866 OTTAWA BEACH RD HOLLAND, MI US 49424 Contact: OIL SAMPLE/PART kyle@yachtbasinmarina.com T: (616)786-2205 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP718610

 Unique No:
 10630052

 Signed:
 Sean Felton

 Report Date:
 01 Sep 2023

## **OIL ANALYSIS REPORT**



