



## MARK THORNDYKE ZF HURTH 20372485 - INBOARD - STARBOARD GEARBOX

Sample No: VPA059319
Oil Type: SAE 30W

SAMPLE INFORM <i>i</i>	ATION			
Sample Number		VPA059319	 	
Sample Date		20 Oct 2023	 	
Machine Hours		341	 	
Oil Hours		90	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
		TTO RUDALE		
OIL CONDITION				
Visc @ 40°C	cSt	■89.5	 	
CONTAMINATION				
Silicon			 	
	ppm	<b>■</b> 7		
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	■0	 	
WEAR METALS				
PQ		<b>13</b>	 	
Iron	ppm	13	 	
Copper	ppm	■24	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	■39	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	<b>■&lt;1</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	10.10.15	= 2222	 	
	ppm	3233		
Magnesium	ppm	<b>21</b>	 	
Zinc	ppm	<b>■</b> 1069	 	
Phosphorus	ppm	<b>■</b> 905	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>416</b>	 	

## **CHICAGO YACHT WORKS**

2550 S ASHLAND AVE CHICAGO, IL US 60608 Contact: JONATHAN PAIGE jonathan@chicagoyachtworks.com T: (312)666-6670 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP1080862

 Unique No:
 10714473

 Signed:
 Sean Felton

 Report Date:
 31 Oct 2023

## **OIL ANALYSIS REPORT**



