



## CLEMENTINE 20005232 - INBOARD - PORT GEARBOX

Sample No: VPA059828

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORMA	ATION			
Sample Number Sample Date Machine Hours Oil Hours Oil Changed Sample Status		VPA059828 25 Oct 2023 16 16 Changed NORMAL	VPA046273  09 Jan 2023 1432  14  Changed  NORMAL	   
OIL CONDITION				
Visc @ 40°C	cSt	■88.3	■91.0	 
CONTAMINATION				
Silicon Sodium Potassium	ppm ppm ppm	□5 □4 □<1	7 2 <1	  
WEAR METALS				
PQ		<b>□</b> 21	<b>□</b> 9	 
Iron	ppm	<b>11</b>	■23	 
Copper	ppm	<b>46</b>	<b>1</b> 7	 
Lead	ppm	<b>5</b> 4	<b>-</b> <1	 
Tin	ppm	<b>0</b>	1	 
Aluminum	ppm	<b>2</b>	7	 
Chromium	ppm	<b>0</b>	<b>2</b>	 
Molybdenum	ppm	<b>104</b>	■50	 
Nickel	ppm	<b>0</b>	<1	 
Titanium	ppm	0	0	 
Silver	ppm	<1	0	 
Manganese	ppm	<b>■</b> <1	<b></b>	 
Vanadium	ppm	0	<1	 
ADDITIVES				
Calcium	ppm	<b>2476</b>	<b>1</b> 527	 
Magnesium	ppm	■36	<b>467</b>	 
Zinc	ppm	<b>1130</b>	<b>1014</b>	 
Phosphorus	ppm	<b>964</b>	■822	 
Barium	ppm	<b>0</b>	<b>0</b>	 
Boron	ppm	<b>7</b>	<b>6</b> 2	 

## The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD
US 21654
Contact: TRACY PELLERIN
tpellerin@hinckleyyachts.com
T: (410)770-4899
F: x:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP592286Unique No:10722983Signed:Don BaldridgeReport Date:01 Nov 2023

## **OIL ANALYSIS REPORT**



