



## JOE ZATTAR 353283 MERCRUISER 20312619 - ZEUS/ZF - PORT TRANSMISSION

Sample No: VPA048448

Oil Type: MERCURY 0W30

SAMPLE INFORMA	ATION			
Sample Number		VPA048448	 	
Sample Date		27 Oct 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
		711.12.111.011		
OIL CONDITION				
Visc @ 40°C	cSt	■39.4	 	
CONTAMINATION				
Silicon	ppm	<b>□</b> 4	 	
Sodium	ppm	<b>0</b>	 	
Potassium	ppm	<b>6</b>	 	
WEAR METALS				
		= 400		
PQ		<b>■</b> 102	 	
Iron	ppm	■ 189 • 336	 	
Copper Lead	ppm	<u> </u>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■2</b>	 	
	ppm	50		
Molybdenum Nickel	ppm		 	
	ppm	<b></b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese Vanadium	ppm	0	 	
vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2258	 	
Magnesium	ppm	11	 	
Zinc	ppm	785	 	
Phosphorus	ppm	729	 	
Barium	ppm	5	 	
Boron	ppm	218	 	

## Skipper Marine of Ohio, LLC

6801 E. Harbor Rd., 6801 East Harbor Rd. MARBLEHEAD, OH US 43440

Contact: Glenn Pollock glenn@skipperbuds.com

T: F:

## Diagnosis

The fluid change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VP494046Unique No:10724360Signed:Don BaldridgeReport Date:03 Nov 2023

## **OIL ANALYSIS REPORT**



