



## LOCKHER H15388 MERCEDES-BENZ MERC ZUES - LOCKHER (S/N NOT GIVEN) - STARBOARD IPS

Sample No: VPA036440
Oil Type: NOT GIVEN

SAMPLE INFORMA	ATION			
Sample Number		VPA036440	 	
Sample Date		01 Nov 2023	 	
Machine Hours		1741	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>■37.1</b>	 	
CONTAMINATION				
Silicon	ppm	4	 	
Sodium	ppm	<b>=</b> 2	 	
Potassium	ppm	<b>2</b>	 	
	ррпп		 	
WEAR METALS				
PQ		<b>27</b>	 	
Iron	ppm	<b>■24</b>	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	8	 	
Tin	ppm	<1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	43	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2027	 	
Magnesium	ppm	8	 	
Zinc	ppm	699	 	
Phosphorus	ppm	641	 	
Barium	ppm	0	 	
Boron	ppm	223	 	
DOTOTT	phili	LLJ		

## Walstrom Marine - 767948

501 Bay Street
HARBOR SPRINGS, MI
US 49740
Contact: RICK HEINY
rheiny@walstrom.com
T:
F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP154879Unique No:10727724Signed:Doug BogartReport Date:07 Nov 2023





