



Sample No: VPA059683

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA059683	 	
Sample Date		06 Nov 2023	 	
Machine Hours		96	 	
Oil Hours		20	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
Sumple Status		HORWAL		
OIL CONDITION				
Visc @ 100°C	cSt	14.2	 	
Base Number (BN)	mg KOH/g	7.5	 	
Oxidation (PA)	%	52	 	
` '				
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	0	 	
Nitration (PA)	%	56	 	
Sulfation (PA)	%	47	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■8	 	
Sodium	ppm	2	 	
Potassium	ppm	■ 3	 	
WEAR METALS				
Iron	ppm	2	 	
Copper	ppm		 	
Lead	ppm	■0	 	
Tin	ppm	0	 	
Aluminum		2	 	
Chromium	ppm	0		
Molybdenum	ppm	□ 75	 	
Nickel	ppm	0	 	
Titanium	ppm	<1		
	ppm			
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2038	 	
Magnesium	ppm	53	 	
Zinc	ppm	1136	 	
Phosphorus	ppm	■952	 	
Barium	ppm	□0	 	
Boron	ppm	105	 	
20.011	77111			

The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD US 21654
Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899
F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VP592286

 Unique No:
 10751215

 Signed:
 Angela Borella

 Report Date:
 21 Nov 2023

OIL ANALYSIS REPORT



