OIL ANALYSIS REPORT

OLD FASHIONED 3739 20025669 - INBOARD - GEARBOX

Sample No: VPA058259

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORM	NATION				
Sample Number		VPA058259	VPA044586	 	
Sample Date		14 Nov 2023	23 Nov 2022	 	The Talaria Compa 202 Banks St., One Li
Machine Hours		956	884	 	
Oil Hours		71	51	 	OXFORD, MD
Oil Changed		Changed	Changed	 	US 21654
Sample Status		NORMAL	NORMAL	 	Contact: TRACY PELL
OIL CONDITION					tpellerin@hinckleyya T: (410)770-4899
Visc @ 40°C	cSt	93.1	94.7	 	F: x:
CONTAMINATIO	N				Diagnosis
Water	%	NEG	NEG	 	Resample at the nex
Silicon	ppm	5	5	 	to monitor.All comp are normal. There is
Sodium	ppm	1	3	 	any contamination i
Potassium	ppm	3	0	 	condition of the oil i
WEAR METALS					the time in service.
PQ		16	7	 	
Iron	ppm	8	9	 	
Copper	ppm	68	59	 	
Lead	ppm	7 3	89	 	
Tin	ppm	■ <1	1	 	
Aluminum	ppm	∎1	<1	 	
Chromium	ppm	0	 <1	 	
Molybdenum	ppm	🔲 109	113	 	
Nickel	ppm	0	<1	 	
Titanium	ppm	<1	0	 	
Silver	ppm	<1	<1	 	
Manganese	ppm	0	 <1	 	
Vanadium	ppm	0	0	 	_
ADDITIVES					
Calcium	ppm	2631	2590	 	
Magnesium	ppm	34	62	 	
Zinc	ppm	1161	1148	 	
Phosphorus	ppm	1016	1027	 	
Barium	ppm	0	0	 	
Boron	ppm	20	5	 	

VOLVO PENTA

2 Banks St., One Little Harbor Landing XFORD, MD S 21654 ontact: TRACY PELLERIN ellerin@hinckleyyachts.com (410)770-4899 x:

iagnosis

esample at the next service interval o monitor.All component wear rates re normal. There is no indication of ny contamination in the oil. The ondition of the oil is acceptable for he time in service.


Depot:	VP592286		
Unique No:	10751870		
Signed:	Jonathan Hester		
Report Date:	22 Nov 2023		

Contact/Location: TRACY PELLERIN - VP592286

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP592286 [WUSCAR] 06012726 (Generated: 11/22/2023 15:35:50) Rev: 1

Contact/Location: TRACY PELLERIN - VP592286