



UPSHORT 10072 5KS478 - INBOARD - STARBOARD GEARBOX

Sample No: VPA059308
Oil Type: SAE 40W

SAMPLE INFORMA	ATION			
Sample Number		VPA059308	 	
Sample Date		06 Nov 2023	 	
Machine Hours		505	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
		HORWAL		
OIL CONDITION				
Visc @ 40°C	cSt	122	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	142 3	 	
Sodium	ppm	0	 	
Potassium	ppm	2	 	
WEAR METALS				
PQ		14	 	
Iron	ppm	42	 	
Copper	ppm	■89	 	
Lead	ppm	■ 6	 	
Tin	ppm	■0	 	
Aluminum	ppm	■ 1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	69	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	■ <1	 	
Silver	ppm	0	 	
Manganese	ppm	- <1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2284	 	
Magnesium	ppm	126	 	
Zinc	ppm	1020	 	
Phosphorus	ppm	■885	 	
Barium	ppm	0	 	
Boron	ppm	■ 4	 	

The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD US 21654 Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899 F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286
Unique No: 10751871
Signed: Jonathan Hester
Report Date: 22 Nov 2023

OIL ANALYSIS REPORT



