## **OIL ANALYSIS REPORT**

## HALEYON 20175670 - INBOARD - PORT GEARBOX

Sample No: VPA058113

Oil Type: PENNZOIL DEXRON MERCON ATF FLUID

SAMPLE INFORM	ATION					
	ATION					
Sample Number		VPA058113				The Talaria Company
Sample Date		30 Oct 2023				202 Banks St., One Little Harbor Landing
Machine Hours		628				OXFORD, MD
Oil Hours		50				US 21654
Oil Changed		Changed				Contact: TRACY PELLERIN
Sample Status		NORMAL				tpellerin@hinckleyyachts.com
OIL CONDITION						T: (410)770-4899 F: x:
Visc @ 40°C	cSt	26.4				1. <b>A</b> .
CONTAMINATION						Diagnosis
Wator	0/					Resample at the next service interval
Water Silicon	%	NEG				to monitor.All component wear rates
	ppm	3				are normal. There is no indication of
Sodium	ppm	0				any contamination in the oil. The
Potassium	ppm	<b>1</b>				condition of the oil is acceptable for the time in service.
WEAR METALS						the time in service.
PQ		<b>1</b> 4				
Iron	ppm	<b>1</b> 4				
Copper	ppm	<b>16</b>				
Lead	ppm	9				
Tin	ppm	0				
Aluminum	ppm	<b>1</b>				
Chromium	ppm	0				
Molybdenum	ppm	1				
Nickel	ppm	0				
Titanium	ppm	<1				
Silver	ppm	0				
Manganese	ppm	0				
Vanadium	ppm	0				
ADDITIVES						
Calcium	ppm	119				
Magnesium	ppm	3				
Zinc	ppm	9				
Phosphorus	ppm	228				
Barium	ppm	0				
Boron	ppm	121				



 Depot:
 VP592286

 Unique No:
 10751873

 Signed:
 Jonathan Hester


 Report Date:
 22 Nov 2023

Contact/Location: TRACY PELLERIN - VP592286

## **OIL ANALYSIS REPORT**



## GRAPHS



Report Id: VP592286 [WUSCAR] 06012729 (Generated: 11/22/2023 15:36:12) Rev: 1

Contact/Location: TRACY PELLERIN - VP592286