



SAMBA 20043257 - INBOARD GEARBOX

Sample No: VPA056895

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORM	ATION			
Sample Number		VPA056895	VPA044661	
Sample Date		03 Nov 2023	02 Nov 2022	
Machine Hours		769	537	
Oil Hours		233	0	
Oil Changed		Changed	N/A	
Sample Status		NORMAL	ATTENTION	
·	_	110111111111	711121111011	_
OIL CONDITION				
Visc @ 40°C	cSt	79.3	□ 63.8	
CONTAMINATION				
Water	%	NEG	NEG	
Silicon	ppm	■ 4	4	
Sodium	ppm	■0	2	
Potassium	ppm	■ 3	- <1	
WEAR METALS				
PQ		29	■32	
Iron	ppm	■28	1 9	
Copper	ppm	■82	<u> </u>	
Lead	ppm	55	△ 70	
Tin	ppm	■3	6	
Aluminum	ppm	■1	2	
Chromium	ppm	■ 0	<1	
Molybdenum	ppm	■ 97	37	
Nickel	ppm	■0	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	■ 0	<1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	2495	2264	
Magnesium	ppm	■ 39	61	
Zinc	ppm	1120	1062	
Phosphorus	ppm	1012	969	
Barium	ppm	0	0	
Boron	ppm	■ 34	48	

The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD US 21654
Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899
F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP592286Unique No:10751874Signed:Jonathan HesterReport Date:22 Nov 2023

OIL ANALYSIS REPORT



