



HARPOON - BARBARA ANNE 20319685 - INBOARD GEARBOX

Sample No: VPA056894

Oil Type: SHELL ROTELLA T 30

CAMPLE INFORM	IRTION			
SAMPLE INFORM	1A I IUN			
Sample Number		VPA056894	VPA043780	
Sample Date		03 Nov 2023	28 Dec 2021	
Machine Hours		202	187	
Oil Hours		8	6	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CONDITION				
Visc @ 40°C	cSt	■92.5	■94.7	
CONTAMINATIO	N			
Water	%	NEG	NEG	
Silicon	ppm	5	4	
Sodium	ppm	0	3	
Potassium	ppm	1	0	
WEAR METALS				
PQ		1 2	□ 15	
Iron	ppm	<u></u> 6	7	
Copper	ppm	 199	■ 195	
Lead	ppm		- <1	
Tin	ppm	■<1	- <1	
Aluminum	ppm	1	- <1	
Chromium	ppm	0	<1	
Molybdenum	ppm	112	115	
Nickel	ppm	■ 0	0	
Titanium	ppm	<1	0	
Silver	ppm	0	<1	
Manganese	ppm	0	- <1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	2472	□2626	
Magnesium	ppm	<u></u>	61	
Zinc	ppm	1070	1117	
Phosphorus	ppm	944	1018	
Barium	ppm	■0	0	
Boron	ppm	2	1	

The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD
US 21654
Contact: TRACY PELLERIN
tpellerin@hinckleyyachts.com
T: (410)770-4899
F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286
Unique No: 10751878
Signed: Jonathan Hester
Report Date: 22 Nov 2023

OIL ANALYSIS REPORT



