



## 1140739506 - GENSET

Sample No: VPA059853

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA059853	 	
Sample Date		27 Nov 2023	 	
Machine Hours		1250	 	
Oil Hours		191	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.6</b>	 	
Base Number (BN)	mg KOH/g	■8.3	 	
Oxidation (PA)	%	63	 	
CONTAMINATION				
	0/	NEG		
Water	%	NEG	 	
Soot %	%	<b>■</b> 0.1	 	
Nitration (PA) Sulfation (PA)	%	53 55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon		< 1.0 <b>■</b> 5	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>8</b>	 	
	ррпп			
WEAR METALS				
Iron	ppm	<b>■</b> 5	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>■</b> 2	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> 0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>2081</b>	 	
Magnesium	ppm	<b>11</b>	 	
Zinc	ppm	<b>1083</b>	 	
Phosphorus	ppm	925	 	
Barium	ppm	■0	 	
Boron	ppm	<b>180</b>	 	
201011	Phili			

## The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD
US 21654
Contact: TRACY PELLERIN
tpellerin@hinckleyyachts.com
T: (410)770-4899
F: x:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP592286Unique No:10767894Signed:Jonathan HesterReport Date:07 Dec 2023

## **OIL ANALYSIS REPORT**



