

OIL ANALYSIS REPORT

VOLVO PENTA

EAST OF WEST 3820 70417 - PORT DIESEL ENGINE

Sample No: VPA047821
Oil Type: SHELL 15W40

SAMPLE INFORMATION

Sample Number	VPA047821	---	---	---
Sample Date	20 Nov 2023	---	---	---
Machine Hours	93	---	---	---
Oil Hours	26	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 13.6	---	---	---
Base Number (BN)	mg KOH/g	█ 8.6	---	---	---
Oxidation (PA)	%	67	---	---	---

CONTAMINATION

Water	%	NEG	---	---	---
Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	53	---	---	---
Sulfation (PA)	%	56	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 1	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 13	---	---	---

WEAR METALS

Iron	ppm	█ 8	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 2	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 4	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	█ 2168	---	---	---
Magnesium	ppm	█ 9	---	---	---
Zinc	ppm	█ 1277	---	---	---
Phosphorus	ppm	█ 1036	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 143	---	---	---

The Talaria Company

202 Banks St., One Little Harbor Landing
OXFORD, MD
US 21654
Contact: TRACY PELLERIN
tpellerin@hinckleyyachts.com
T: (410)770-4899
F: x:

Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VP592286
Unique No: 10767905
Signed: Sean Felton
Report Date: 05 Dec 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

