OIL ANALYSIS REPORT

BLUE BIRD 10072 2147851 - INBOARD - STARBOARD GEARBOX

Sample No: VPA059858

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORMATION

						1
Sample Number		VPA059858				
Sample Date		27 Nov 2023				The Talaria Company
Machine Hours		983				202 Banks St., One Little Harbor Landin
Oil Hours		0				OXFORD, MD
Oil Changed		N/A				US 21654
Sample Status		NORMAL				Contact: TRACY PELLERIN
						tpellerin@hinckleyyachts.com
OIL CONDITION						T: (410)770-4899
Visc @ 40°C	cSt	96.7				F: x:
						Diagnosis
CONTAMINATIO	Ň					Diagnosis
Water	%	NEG				Resample at the next service interval
Silicon	ppm	3				to monitor.All component wear rates are normal. There is no indication of
Sodium	ppm	3				any contamination in the oil. The
Potassium	ppm					condition of the oil is acceptable for
	pp					the time in service.
WEAR METALS						
PQ		21				
Iron	ppm	121				
Copper	ppm	38				
Lead	ppm	2				
Tin	ppm	0				
Aluminum	ppm	2				
Chromium	ppm	0				
Molybdenum	ppm	114				
Nickel	ppm	0				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	 <1				
Vanadium	ppm	0				
ADDITIVES						
Calcium	ppm	2760				
Magnesium	ppm	19				
Zinc	ppm	1202				
Phosphorus	ppm	1026				
Barium	ppm	0				
Boron	ppm	2				
DOIOII	ppiii	L				



 Depot:
 VP592286

 Unique No:
 10768647

 Signed:
 Don Baldridge


 Report Date:
 06 Dec 2023

Contact/Location: TRACY PELLERIN - VP592286

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP592286 [WUSCAR] 06024147 (Generated: 12/06/2023 11:41:44) Rev: 1

Contact/Location: TRACY PELLERIN - VP592286