OIL ANALYSIS REPORT

MIKE SUZUKI ACN 100600806 - OUTBOARD GEARBOX

Sample No: VPA012850

Oil Type: SUZUKI 10W40

SAMPLE INFORMATION VPA012850 Sample Number Sample Date 04 Dec 2023 Machine Hours 0 SOUTH AMBOY, NJ 50 **Oil Hours** US 08879 Oil Changed Not Changd MARGINAL Sample Status T: **OIL CONDITION** F: Visc @ 40°C cSt 76.4 CONTAMINATION Diagnosis % Water **0.194** Silicon ppm 13 Sodium 3 ppm Potassium ppm 1 WEAR METALS PO 16 9 Iron ppm Copper 1 ppm Lead **||** <1 ppm 0 🔲 Tin ppm 1 Aluminum ppm Chromium ppm ■ <1 Molybdenum <1 ppm Nickel ppm 0 Titanium 12 ppm Silver 0 ppm Manganese <1 ppm Vanadium <1 ppm **ADDITIVES** 2038 Calcium ppm 4 Magnesium ppm Zinc ppm 1034 879 Phosphorus ppm Barium 0 ppm 177 Boron ppm



Lockwood Boat Works Inc 1825 Highway 35, Morgan Contact: Ellen Lockwood ellen@lockwoodboatworks.com;maryann@lockwoodboatworks.com

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a trace of moisture present in the oil. The condition of the oil is acceptable for the time in service.


Depot: VP153187 Unique No: 10777926 Signed: Jonathan Hester **Report Date:** 11 Dec 2023

Contact/Location: Ellen Lockwood - VP153187

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP153187 [WUSCAR] 06028135 (Generated: 12/11/2023 13:15:28) Rev: 1

Contact/Location: Ellen Lockwood - VP153187