



BRUCE DYER KOHLER SGM32LFW5 - STARBOARD GENSET

Report Id: VP568144 [WUSCAR] 06029031 (Generated: 12/12/2023 00:07:38) Rev: 1

Sample No: VPA031139

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA031139	VPA037604	
Sample Date		06 Dec 2023	18 Aug 2021	
Machine Hours		1385	893	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CONDITION				
Visc @ 100°C	cSt	14.1	14.7	
Base Number (BN)	mg KOH/g	■ 9.2		
Oxidation (PA)	%	60	53	
CONTAMINATION				
Water	%	NEG	NEG	
Soot %	%	■0.1	0.8	
Nitration (PA)	%	53	50	
Sulfation (PA)	%	51	56	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	<1.0	
Silicon	ppm	■4	7	
Sodium	ppm	1	2	
Potassium	ppm	1	6	
	PPIII			
WEAR METALS				
Iron	ppm	4	1 2	
Copper	ppm	■0	- <1	
Lead	ppm	0	< 1	
Tin	ppm	■0	<1	
Aluminum	ppm	1	0	
Chromium	ppm	■<1	 <1	
Molybdenum	ppm	47	■8	
Nickel	ppm	■ 0	0	
Titanium	ppm	■0	<u> </u>	
Silver	ppm	O	<1	
Manganese	ppm	■0	- <1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	1338	□ 2139	
Magnesium	ppm	■ 558	1 01	
Zinc	ppm	■ 1124	1115	
Phosphorus	ppm	■ 978	957	
Barium	ppm	3	□ 0	
Boron	ppm	38	269	
50.011	PPIII			

COASTAL CAROLINA YACHT SALES

145 LOCKWOOD BLVD CHARLESTON, SC US 29403 Contact: STEVE VASAS steve@ccyachtsales.com T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP568144Unique No:10778822Signed:Doug BogartReport Date:11 Dec 2023

OIL ANALYSIS REPORT



