## **OIL ANALYSIS REPORT**

#### PRECIOUS TIME 10072 20400856 - INBOARD - PORT GEARBOX

Sample No: VPA060628

**Oil Type:** SHELL ROTELLA T 30

#### SAMPLE INFORMATION VPA060628 VPA046279 Sample Number Sample Date 14 Dec 2023 29 Dec 2022 Machine Hours 144 79 0 **Oil Hours** 65 Oil Changed N/A Changed NORMAL Sample Status NORMAL **OIL CONDITION** F: x: Visc @ 40°C cSt 87.9 88.4 CONTAMINATION % Water NEG NEG Silicon 5 ppm 5 Sodium 0 6 ppm Potassium ppm 2 0 WEAR METALS PO 15 18 Iron ppm 12 12 Copper 162 155 ppm Lead 1 □ <1 ppm 0 Tin 1 ppm 3 Aluminum ppm 3 Chromium 0 ppm ■ <1 103 78 Molybdenum ppm 0 Nickel ppm <1 Titanium 0 ppm <1 Silver 0 <1 ppm Manganese ■ <1 < 1</p> ppm Vanadium 0 0 ppm **ADDITIVES** 2072 Calcium 1194 ppm Magnesium ppm 229 445 Zinc ppm 1046 711 Phosphorus 961 671 ppm Barium ppm 9 < 1 Boron 89 178



The Talaria Company 202 Banks St., One Little Harbor Landing OXFORD, MD US 21654

Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286 Unique No: 10794844 Signed: Angela Borella **Report Date:** 21 Dec 2023


ppm

Contact/Location: TRACY PELLERIN - VP592286

# **OIL ANALYSIS REPORT**



### GRAPHS



Report Id: VP592286 [WUSCAR] 06039615 (Generated: 12/22/2023 18:05:21) Rev: 1

Contact/Location: TRACY PELLERIN - VP592286