



## KEITH WILLIAMS GB6018 PANDA 2000750 - PORT GENSET

Sample No: VPA049757

Oil Type: DIESEL ENGINE OIL SAE 15W40

Report Id: VP531377 [WUSCAR] 06041914 (Generated: 12/22/2023 14:06:21) Rev: 1

SAMPLE INFORMAT	TION			
Sample Number		VPA049757	 	
Sample Date		14 Dec 2023	 	
Machine Hours		480	 	
Oil Hours		100	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
Sample Status		NORWAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.1</b>	 	
Base Number (BN)	mg KOH/g	<b>7.6</b>	 	
Oxidation (PA)	%	67	 	
CONTAMINATION				
CONTRIBUTION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	57	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■</b> 9	 	
Sodium	ppm	<b>■&lt;1</b>	 	
Potassium	ppm	<b>5</b>	 	
WEAR METALS				
Iron	ppm	<u> </u>	 	
Copper	ppm	■0	 	
Lead	ppm	■0	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>0</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>2277</b>	 	
Magnesium	ppm	<b>39</b>	 	
Zinc	ppm	<b>■</b> 1205	 	
Phosphorus	ppm	<b>1007</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>■</b> 159	 	
DOTOTI	ppiii	<u> </u>		

## **GRAND BANKS**

450 SW SALEM RD STUART, FL US 34994 Contact: ROBERT ANTONA roberta@gbmarinegroup.com T: (609)384-5290 F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP531377

 Unique No:
 10802522

 Signed:
 Sean Felton

 Report Date:
 22 Dec 2023

## **OIL ANALYSIS REPORT**



