



## R16874 NORTHERN LIGHTS 008008 - GENSET

Sample No: VPA051842

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

SAMPLE INFORMAT	TION			
Sample Number		VPA051842	 	
Sample Date		05 Feb 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
		HORWAL		
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.6</b>	 	
Base Number (BN)	mg KOH/g	<b>10.0</b>	 	
Oxidation (PA)	%	51	 	
CONTAMINATION				
	0/	NEC		
Water Soot %	%	NEG	 	
		<b>■</b> 0 35	 	
Nitration (PA) Sulfation (PA)	%	49		
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon		■4	 	
Sodium	ppm	■ <del>-</del>	 	
Potassium	ppm	<b>■ &lt;1</b>	 	
	PPIII			
WEAR METALS				
Iron	ppm	<b>0</b>	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	<b>■</b> 55	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	<b>1</b> <1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>■</b> 929	 	
Magnesium	ppm	<b>934</b>	 	
Zinc	ppm	<b>1222</b>	 	
Phosphorus	ppm	<b>1021</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>2</b>	 	

Western Branch Diesel, Inc. - VP527273

3504 SHIPWRIGHT ST PORTSMOUTH, VA US 23703 Contact: GEORGE ROGIC

grogic@wbdiesel.com

T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP155396Unique No:10863241Signed:Doug BogartReport Date:09 Feb 2024

## **OIL ANALYSIS REPORT**



