



BRIAN GROTTY 534297 NORTHERN LIGHTS 7732-54691 - GENSET

Sample No: VPA055764

Oil Type: SHELL ROTELLA T4 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA055764	 	
Sample Date		15 Feb 2024	 	
Machine Hours		1430	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	14.5	 	
Base Number (BN)	mg KOH/g	■8.7	 	
Oxidation (PA)	%	65	 	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	43	 	
Sulfation (PA)	%	56	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■3	 	
Sodium	ppm	■ 3	 	
Potassium	ppm	■8	 	
WEAR METALS				
Iron	ppm	■ 4	 	
Copper	ppm	<1	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■ 3	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■ 3	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	<1	 	
Silver	ppm	■ 0	 	
Manganese	ppm	■ 0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	1919	 	
Magnesium	ppm	42	 	
Zinc	ppm	■ 1092	 	
Phosphorus	ppm	955	 	
Barium	ppm	10	 	
Boron	ppm	169	 	
	77			

Jas Marine Service Inc.

1009 Newman RD. LAKE PARK, FL US 33403 Contact: DEBBIE debbie@jasmarine.com T: (561)844-3224 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP152963Unique No:10885578Signed:Don BaldridgeReport Date:20 Feb 2024

Contact/Location: DEBBIE ? - VP152963





