



## JEREMY ASARESE HURTH HURTH ZF63 (S/N NOT GIVEN) - GEARBOX

Sample No: VPA046105

Oil Type: PENNZOIL MULTI VEHICLE ATF FLUID

CAMPLE INFORM	IA TION			
SAMPLE INFORM	ATIUN			
Sample Number		VPA046105	 	
Sample Date		20 Dec 2023	 	
Machine Hours		700	 	
Oil Hours		100	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>□</b> 28.7	 	
CONTAMINATION	1			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
PQ		<b>1</b> 9	 	
Iron	ppm	<b>■</b> 55	 	
Copper	ppm	<b>126</b>	 	
Lead	ppm	<b>A</b> 28	 	
Tin	ppm	<b>■3</b>	 	
Aluminum	ppm	<b>4</b>	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>-&lt;</b> 1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	67	 	
Magnesium	ppm	3	 	
Zinc	ppm	119	 	
Phosphorus	ppm	196	 	
Barium	ppm	8	 	
Boron	ppm	73	 	

## Saba Marine LLC

390 Prim Rd COLCHESTER, VT US 05446

Contact: JT ASARESE PARTS@SABAMARINEVT.COM

T: (802)863-1148 F: (802)863-8201

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Clutch wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP751561Unique No:10916700Signed:Jonathan HesterReport Date:12 Mar 2024

## **OIL ANALYSIS REPORT**



