



## BRUCE TANNEHILL 44326 KOHLER 335GGMJH0006 - GENSET

Sample No: VPA055118

Oil Type: SHELL ROTELLA T4 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA055118	 	
Sample Date		05 Mar 2024	 	
Machine Hours		115	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL COMPLETION				
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.6</b>	 	
Base Number (BN)	mg KOH/g	■8.2	 	
Oxidation (PA)	%	67	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	50	 	
Sulfation (PA)	%	54	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	▲ 115	 	
Sodium	ppm	<u> </u>	 	
Potassium	ppm	<b>3</b>	 	
WEAR METALS		_		
MENK METAL2				
Iron	ppm	<b>■</b> 9	 	
Copper	ppm	■8	 	
Lead	ppm	■1	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>■</b> 3	 	
Chromium	ppm	<b>■</b> 2	 	
Molybdenum	ppm	■37	 	
Nickel	ppm	<b>□</b> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	<1	 	
ADDITIDDA				
Calcium	ppm	<b>1302</b>	 	
Magnesium	ppm	<b>722</b>	 	
Zinc	ppm	<b>1091</b>	 	
Phosphorus	ppm	■936	 	
Barium	ppm	□0	 	
Boron	ppm	<b>51</b>	 	

## **COASTAL CAROLINA YACHT SALES**

145 LOCKWOOD BLVD CHARLESTON, SC US 29403 Contact: STEVE VASAS steve@ccyachtsales.com T: F:

## Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Elemental level of silicon (Si) above normal indicating ingress of seal material. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP568144Unique No:10928134Signed:Don BaldridgeReport Date:18 Mar 2024





