

OIL ANALYSIS REPORT

VOLVO PENTA

D. BOMAR NORTHERN LIGHTS K05508 - GENSET

Sample No: VPA056850

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMATION

Sample Number	VPA056850	---	---	---
Sample Date	11 Apr 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 14.2	---	---	---
Base Number (BN)	mg KOH/g	█ 8.2	---	---	---
Oxidation (PA)	%	66	---	---	---

CONTAMINATION

Water	%	NEG	---	---	---
Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	54	---	---	---
Sulfation (PA)	%	55	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	< 1.0	---	---	---
Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 6	---	---	---

WEAR METALS

Iron	ppm	█ 12	---	---	---
Copper	ppm	█ 2	---	---	---
Lead	ppm	█ < 1	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 8	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	█ 2191	---	---	---
Magnesium	ppm	█ 49	---	---	---
Zinc	ppm	█ 1128	---	---	---
Phosphorus	ppm	█ 863	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 211	---	---	---

Aqua Yacht Harbor Marina
3832 Hwy. 25 North, 3832 Hwy. 25 North
IUKA, MS
US 38852
Contact: DENNIS KANIZAI
dkanizai@shmarinas.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP299833
Unique No: 10980211
Signed: Don Baldrige
Report Date: 18 Apr 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

