



## JOHN BENZ DANIEL/502792 VOLVO PENTA 3102242338 - STERNDRIVE - PORT GEARBOX

Sample No: VPA053119

**Oil Type:** VOLVO PENTA GL-5 SAE 75W90

SAMPLE INFORM	ATION			
	ATTUN			
Sample Number		VPA053119	 	
Sample Date		24 Mar 2024	 	
Machine Hours		684	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>124</b>	 	
CONTAMINATION				
Water	%	<b>▲</b> 1.58	 	
Silicon	ppm	<b>■5</b>	 	
Sodium	ppm	<b>62</b>	 	
Potassium	ppm	<b>4</b>	 	
	<b>PP</b>			
WEAR METALS				
PQ		<b>25</b>	 	
Iron	ppm	<b>423</b>	 	
Copper	ppm	<b>■</b> 3	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>2</b> 9	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	<b>■1</b>	 	
Nickel	ppm	<b>4</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>6</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>1</b> 6	 	
Magnesium	ppm	<b>■</b> 17	 	
Zinc	ppm	<b>1</b> 43	 	
Phosphorus	ppm	<b>1439</b>	 	
Barium	ppm	■0	 	
Boron	ppm	■324	 	
20.011	PPIII			

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107 Contact: WILLOW YANARELLA

service@coastalmarineengine.com T: (206)784-3703

T: (206) /84-3 /03 F: (206) 784-8823

## Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Appearance is hazy. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

 Depot:
 VP794951

 Unique No:
 10990220

 Signed:
 Don Baldridge

 Report Date:
 23 Apr 2024

## **OIL ANALYSIS REPORT**



