



## ERIK ASKUSLAPPFISK EVAN/503072 VOLVO PENTA 3020312015 - STERNDRIVE - GEARBOX

Sample No: VPA061999

Oil Type: VOLVO PENTA GL-5 SAE 75W140

SAMPLE INFORM	ATION			
SAMPLE INFURM	ATIUN			
Sample Number		VPA061999	 	
Sample Date		06 May 2024	 	
Machine Hours		3313	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>△</b> 103	 	
CONTAMINATION				
Water	%	<b>△</b> 0.362	 	
Silicon	ppm	<b>4</b>	 	
Sodium	ppm	<b>■1</b>	 	
Potassium	ppm	 <1	 	
	ррпп			
WEAR METALS				
PQ		<b>1</b> 5	 	
Iron	ppm	<b>▲</b> 342	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	■3	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>6</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>6</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>43</b>	 	
Magnesium	ppm	■0	 	
Zinc	ppm	■37	 	
Phosphorus	ppm	<b>1444</b>	 	
Barium	ppm	<b>-</b> <1	 	
Boron	ppm	■325	 	
_ 3	PPIII			

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107 Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is severe. There is a moderate concentration of water present in the oil. The oil viscosity is lower than normal. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

 Depot:
 VP794951

 Unique No:
 11018946

 Signed:
 Sean Felton

 Report Date:
 13 May 2024

## **OIL ANALYSIS REPORT**



