[[MORTON]] ONAN 1140743063 - GENSET

Sample No: VPA061576

Zinc

Barium

Boron

Phosphorus

Oil Type: DIESEL ENGINE OIL SAE 15W40

CAMPLEIN		ON			
SAMPLE IN	IFURIVIATI				
Sample Number		VPA061576			
Sample Date		07 May 2024			
Machine Hours		1430			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 100°C	cSt	■13.6			
Base Number (BN)	mg KOH/g	■8.7			
Oxidation (PA)	%	69			
CONTAMINATION					
Water	%	NEG			
Soot %	%	■ 0.1			
Nitration (PA)	%	56			
Sulfation (PA)	%	56			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	6			
Sodium	ppm	4			
Potassium	ppm	2			
WEAR MET	ALS				
Iron	ppm	6			
Copper	ppm	□ <1			
Lead	ppm	2			
Tin	ppm	□ <1			
Aluminum	ppm	■ <1			
Chromium	ppm	□<1			
Molybdenum	ppm	■45			
Nickel	ppm	0			
Titanium		□ <1			
Silver	ppm	0			
Manganese	ppm	□ <1			
Vanadium	ppm	0			
variaululli	ppm	U			
ADDITIVES					
Calcium	ppm	1364			
Magnesium	ppm	774			

16:33:26) Rev: 1

994

■833

0

62

ppm

ppm

ppm

ppm

SUNCOAST DIESEL MARINE

6341 PORTER ROAD, SUITE 6 SARASOTA, FL US 34240 Contact: JOSHUA joshua@suncoastdmi.com T: (941)342-0033 F: (941)342-0088

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP705283Unique No:11019258Signed:Doug BogartReport Date:09 May 2024

Contact/Location: JOSHUA? - VP705283

