



BRIAN WHELAN 506145 ZF 20336297 - INBOARD - PORT GEARBOX

Sample No: VPA053075
Oil Type: RUBRO SAE 30

SAMPLE INFORMA	ATION			
Sample Number		VPA053075	VPA031707	
Sample Date		08 May 2024	05 Oct 2020	
Machine Hours		301	153	
Oil Hours		144	153	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
OIL CONDITION				
Visc @ 40°C	cSt	73.3	□ 74.6	
CONTAMINATION				
Water	%	NEG	NEG	
Silicon	ppm	11	9	
Sodium	ppm	7	5	
Potassium	ppm	2	0	
WEAR METALS				
PQ		■34	□ 58	
Iron	ppm	■ 86	7 1	
Copper	ppm	126	6 2	
Lead	ppm	6	9	
Tin	ppm	<u> </u>	0	
Aluminum	ppm	■8	9	
Chromium	ppm	■<1	<1	
Molybdenum	ppm	39	3 6	
Nickel	ppm	■0	<1	
Titanium	ppm	<1	- <1	
Silver	ppm	0	0	
Manganese	ppm	1	<u> </u>	
Vanadium	ppm	<1	0	
ADDITIVES				
Calcium	ppm	3169	■3260	
Magnesium	ppm	14	■14	
Zinc	ppm	1024	■980	
Phosphorus	ppm	1002	■855	
Barium	ppm	2	2	
Boron	ppm	540	■399	

Jefferson Beach Yacht Sales Inc

24400 Jefferson Ave.
SAINT CLAIR SHORES, MI
US 48080
Contact: DENNIS BUTT
dbutt@jbys.com
T: (866)490-5297
F:

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP297371

 Unique No:
 11021909

 Signed:
 Sean Felton

 Report Date:
 14 May 2024

OIL ANALYSIS REPORT



