



## KEITH WILLIAMS GB6018 TWIN DISC 2437830 - INBOARD - PORT GEARBOX

Sample No: VPA054956

Oil Type: MOBIL MOBILFLUID 424

SAMPLE INFORM	IATION			
	ATION			
Sample Number		VPA054956	VPA049510	 
Sample Date		03 May 2024	14 Dec 2023	 
Machine Hours		0	662	 
Oil Hours		0	200	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CONDITION				
Visc @ 40°C	cSt	<b>49.6</b>	<b>47.0</b>	 
CONTAMINATION	1			
Water	%	NEG	NEG	 
Silicon	ppm	■10	<b>1</b> 1	 
Sodium	ppm	<b>5</b>	<b>5</b>	 
Potassium	ppm	<b>0</b>	<b>2</b>	 
WEAR METALS				
PQ		<b>1</b> 5	<b>1</b> 20	 
Iron	ppm	<b>10</b>	□21	 
Copper	ppm	<b>65</b>	<b>1</b> 55	 
Lead	ppm	<b>2</b>	<b>6</b>	 
Tin	ppm	<b>■&lt;1</b>	<b>0</b>	 
Aluminum	ppm	<b>■</b> 4	<b>5</b>	 
Chromium	ppm	<b>■&lt;1</b>	<b>-</b> <1	 
Molybdenum	ppm	<b>■</b> 3	<b>5</b>	 
Nickel	ppm	<b>0</b>	< 1	 
Titanium	ppm	0	<1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>2</b>	<b>-</b> <1	 
Vanadium	ppm	0	0	 
ADDITIVES				
Calcium	ppm	■3504	□3559	 
Magnesium	ppm	<b>■68</b>	■89	 
Zinc	ppm	<b>■1414</b>	■ 1467	 
Phosphorus	ppm	<b>1162</b>	1188	 
Barium	ppm	■0	<b>0</b>	 
Boron	ppm	■136	119	 
	1-1			

## **GRAND BANKS**

450 SW SALEM RD STUART, FL US 34994 Contact: ROBERT ANTONA roberta@gbmarinegroup.com T: (609)384-5290 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP531377Unique No:11023554Signed:Don BaldridgeReport Date:15 May 2024





