



HERLIHY FISCHER PANDA CO2-074-066 - GENSET

Sample No: VPA054223

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	FION			
Sample Number		VPA054223	 	
Sample Date		23 May 2024	 	
Machine Hours		595	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL COMPLETION				
OIL CONDITION				
Visc @ 100°C	cSt	14.54	 	
Base Number (BN)	mg KOH/g	■8.8	 	
Oxidation (PA)	%	46	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	38	 	
Sulfation (PA)	%	42	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	12	 	
Sodium	ppm	2	 	
Potassium	ppm	<u> </u>	 	
WEAR METALS				
	10.10.100		 	
Iron	ppm	4		
Copper Lead	ppm	□ <1 □ <1	 	
Tin	ppm	<u> </u>	 	
Aluminum	ppm	2	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	1 46	 	
Nickel	ppm	■ 40	 	
Titanium	ppm	0	 	
Silver	ppm	■ <1	 	
Manganese	ppm	■ <1	 	
Vanadium	ppm	0	 	
ADDITIODA				
		=4566		
Calcium	ppm	■ 1568	 	
Magnesium	ppm	□ 548	 	
Zinc	ppm	■1114 ■012	 	
Phosphorus Barium	ppm	■912	 	
	ppm	□ 0	 	
Boron	ppm	92	 	

SUNCOAST DIESEL MARINE

6341 PORTER ROAD, SUITE 6 SARASOTA, FL US 34240 Contact: JOSHUA joshua@suncoastdmi.com T: (941)342-0033 F: (941)342-0088

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP705283Unique No:11047676Signed:Doug BogartReport Date:24 May 2024

Contact/Location: JOSHUA? - VP705283

OIL ANALYSIS REPORT



