

Report Id: VP794951 [WUSCAR] 06199876 (Generated: 06/15/2024 02:53:23) Rev: 1



## TREY YACHT MANAGEMENT EVAN/502924 MERCURY 2A533933 - PORT GASOLINE ENGINE

Sample No: VPA061718

Oil Type: MERCURY 25W40

SAMPLE INFORMAT	LIUN			
	TIUN			
Sample Number		VPA061718	 	
Sample Date		29 May 2024	 	
Machine Hours		155	 	
Oil Hours		155	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	16.1	 	
Base Number (BN)	mg KOH/g	■8.4	 	
Oxidation (PA)	%	16	 	
	70			
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■ 0.1	 	
Nitration (PA)	%	9	 	
Sulfation (PA)	%	12	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■ 62</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
Iron	ppm	<b>1</b> 4	 	
Copper	ppm	<b>14</b>	 	
Lead	ppm	<b>4</b>	 	
Tin	ppm	1	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	48	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ZAVITIDDA	pp			
Calcium	ppm	2089	 	
Magnesium	ppm	11	 	
Zinc	ppm	795	 	
Phosphorus	ppm	671	 	
Barium	ppm	<1	 	
Boron	ppm	194	 	

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW

SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP794951Unique No:11061999Signed:Jonathan HesterReport Date:07 Jun 2024

## **OIL ANALYSIS REPORT**



