



JUSTIN DALINGER NORTHERN LIGHTS 8442-40366C - PORT GENSET

Sample No: VPA044034

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA044034	 	
Sample Date		04 Jun 2024	 	
Machine Hours		2606	 	
Oil Hours		150	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
		TTO KIND IL		
OIL CONDITION				
Visc @ 100°C	cSt	13.2	 	
Base Number (BN)	mg KOH/g	■9.1	 	
Oxidation (PA)	%	65	 	
CONTAMINATION				
	0.6	N=0		
Water	%	NEG	 	
Soot %	%	■0.1	 	
Nitration (PA)	%	58	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon Sodium	ppm	5	 	
Potassium	ppm	4	 	
POLASSIUITI	ppm	2	 	
WEAR METALS				
Iron	ppm	5	 	
Copper	ppm	1	 	
Lead	ppm	■<1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	■38	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm		 	
Vanadium	ppm	<1	 	
ADDITIDES				
Calcium	ppm	1770	 	
Magnesium	ppm	441	 	
Zinc	ppm	1236	 	
Phosphorus	ppm	■ 1017	 	
Barium	ppm	■0	 	
Boron	ppm	68	 	

LIBERTY LANDING MARINE

80 AUDREY ZAPP DR
JERSEY CITY, NJ
US 07305
Contact: JOHN PURINTON
jpurinton@suntex.com
T: (201)985-8000
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP454834Unique No:11071671Signed:Sean FeltonReport Date:12 Jun 2024

OIL ANALYSIS REPORT



