



## SURVEY-CANNON SURVEY-CANNON ZF 20350768 - INBOARD - PORT GEARBOX

Sample No: VPA058250
Oil Type: SAE 40W

SAMPLE INFORM	IATION			
Sample Number		VPA058250	 	
Sample Date		25 Jun 2024	 	
Machine Hours		379	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	■85.2	 	
CONTAMINATION	N			
Water	%	NEG	 	
Silicon	ppm	<b>10</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<u> </u>	 	
WEAR METALS				
PQ		<b>59</b>	 	
Iron	ppm	<b>109</b>	 	
Copper	ppm	<b>191</b>	 	
Lead	ppm	<b>■</b> 3	 	
Tin	ppm	<b>13</b>	 	
Aluminum	ppm	<b>■</b> 5	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>19</b>	 	
Nickel	ppm	<b></b>	 	
Titanium	ppm	<b>■</b> <1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	3029	 	
Magnesium	ppm	65	 	
Zinc	ppm	993	 	
Phosphorus	ppm	929	 	
Barium	ppm	<b>1</b>	 	
Boron	ppm	187	 	

## **Suncoast Diesel Marine Inc.**

610 Mount Vernan St OLDSMAR, FL US 34677 Contact: MARK WARREN oldsmar@suncoastdmi.com T: (813)475-5942 F: (813)475-5943

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP945077Unique No:11100774Signed:Doug BogartReport Date:28 Jun 2024

## **OIL ANALYSIS REPORT**



