




# OIL ANALYSIS REPORT

Sample Rating Trend

**NORMAL**



Area  
**[WO#29034]**  
 Machine Id  
**MRP TURBINE GOV SYSTEM**  
 Component  
**Governor System**  
 Fluid

## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor.

### Wear

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the component.

### Fluid Condition

The condition of oil is suitable for further service.

## SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		<b>WC612467</b>	---	---
Sample Date	Client Info		<b>21 Nov 2003</b>	---	---
Machine Age	hrs	Client Info	<b>0</b>	---	---
Oil Age	hrs	Client Info	<b>0</b>	---	---
Oil Changed		Client Info	<b>N/A</b>	---	---
Sample Status			<b>NORMAL</b>	---	---

## CONTAMINATION



	method	limit/base	current	history1	history2
Water	WC Method		<b>NEG</b>	---	---

## SAMPLE IMAGES





	method	limit/base	current	history1	history2
Color				<i>no image</i>	<i>no image</i>
Bottom				<i>no image</i>	<i>no image</i>



# OIL ANALYSIS REPORT



## GRAPHS



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : WC612467 **Received** : 25 Nov 2003  
**Lab Number** : 01071485 **Diagnosed** : 26 Nov 2003  
**Unique Number** : 1641403 **Diagnostician** :  
**Test Package** : IND 2

**NEWFOUNDLAND POWER INC.**  
 50 DUFFY PLACE, PO BOX 8910  
 ST. JOHNS, NL  
 CA A1B 3P6  
 Contact: Paul Martin  
 pmartin@newfoundlandpower.com  
 T:  
 F: (709)737-2926

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.