

OIL ANALYSIS REPORT

Sample Rating Trend



SPIRAL ST7 SCP-197 (S/N TMG17URE0646)

Rear Differential

SHELL SPIRAX HD 85W140 (5 LTR)

Recommendation

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

				May2019		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC113617		
Sample Date		Client Info		23 May 2019		
Machine Age	hrs	Client Info		1405		
Oil Age	hrs	Client Info		1000		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		1602		
Iron	ppm	ASTM D5185(m)	>500	708		
Chromium	ppm	ASTM D5185(m)	>10	2		
Nickel	ppm	ASTM D5185(m)		0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>25	13		
Copper	ppm	ASTM D5185(m)	>100	114		
Tin	ppm	ASTM D5185(m)	>10	5		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		7		
Barium	ppm	ASTM D5185(m)		2		
Molybdenum	ppm	ASTM D5185(m)		<1		
Manganese	ppm	ASTM D5185(m)		6		
Magnesium	ppm	ASTM D5185(m)		2		
Calcium	ppm	ASTM D5185(m)		10		
Phosphorus	ppm	ASTM D5185(m)		1062		
Zinc	ppm	ASTM D5185(m)		67		
Sulfur	ppm	ASTM D5185(m)		31240		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>75	10		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	3		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number **Unique Number**

: WC113617

+02293873

: 4889139

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved : 26 Jun 2019 Diagnosed : 27 Jun 2019 Diagnostician : Kevin Marson

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX Kirkland Lake, ON

CA P2N 3J1 Contact: Jay Gould

Test Package : MOB 1 (Additional Tests: PQ) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Macassa Mobile UGP lanning@agnicoeagle.comT: (705)567-5208

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (705)567-5221