


OIL ANALYSIS REPORT

Sample Rating Trend



WATER



RBK G2 TURB

Component **Bearing**

MOBIL DTE OIL HVY MEDIUM (12 GAL)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We recommend that you drain the oil from the component if this has not already been done. We recommend that you change the oil. We recommend an early resample to monitor this condition. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of laboratory tests is based on sample, as received from client. Source of sample and sampling technique cannot be verified.

Wear

Copper ppm levels are abnormal. Bearing wear is indicated.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition

The white residue present in the sample is oil additive precipitate. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0445222	WC0327885	WC0316760
Sample Date		Client Info		03 Mar 2022	15 Feb 2021	09 Dec 2020
Machine Age	mths	Client Info		24	24	0
Oil Age	mths	Client Info		0	24	22
Oil Changed		Client Info		N/A	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>63	0	<1	<1
Chromium	ppm	ASTM D5185(m)		0	0	0
Nickel	ppm	ASTM D5185(m)		0	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)	>2	0	0	0
Lead	ppm	ASTM D5185(m)	>161	39	18	18
Copper	ppm	ASTM D5185(m)	>13	<u> </u>	<1	<1
Tin	ppm	ASTM D5185(m)	>27	0	<1	<1
Antimony	ppm	ASTM D5185(m)		<1	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		0	0	<1
Calcium	ppm	ASTM D5185(m)		<1	<1	<1
Phosphorus	ppm	ASTM D5185(m)		128	128	112
Zinc	ppm	ASTM D5185(m)		57	41	42
Sulfur	ppm	ASTM D5185(m)		543	2159	2135
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>12	<1	1	1
Sodium	ppm	ASTM D5185(m)		0	0	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.12	0.10	0.13



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: WC0445222

: 02481117 : 5382054

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved Diagnosed

: 07 Apr 2022 Diagnostician : Kevin Marson

: 04 Apr 2022

Test Package: IND 2 (Additional Tests: Bottom, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NEWFOUNDLAND POWER INC.

50 DUFFY PLACE, PO BOX 8910 ST. JOHNS, NL CA A1B 3P6

Contact: Paul Martin pmartin@newfoundlandpower.com

F: (709)737-2926

T: