

FUEL REPORT

APTUM [146797] FIRE PUMP Component

Diesel Fuel

No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

DIAGNOSIS

Recommendation

Laboratory test indicate that this fuel is suitable for use and meets all test requirements. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We advise that you filter this fluid before use. We recommend an early resample to monitor this condition.

Corrosion

{not applicable}

Contaminants

There is a moderate amount of particulates (2 to 100 microns in size) present in the fuel. The water content is negligible.

Fuel Condition

The fuel is still serviceable provided that the contaminant(s) can be reduced to acceptable levels. All laboratory tests indicate that this sample meets specifications for No.2 ultra-low-sulfur diesel fuel (US EPA/CGSB-3.517-3 type B).



Particles >71µm

Oil Cleanliness

ASTM D7647

ISO 4406 (c)

>3

>18/16/13 🔺

0


18/17/14

▲ 19/17/12 Contact/Location: Elisia Johnson - CUMMISGEN

0



FUEL REPORT



Contact/Location: Elisia Johnson - CUMMISGEN