

PROBLEM SUMMARY

GFL 122 Arrow Road - C13100


AG173

Component **Hydraulic System**

NOT GIVEN (--- GAL)

Sample Rating Trend ISO Aug/223

COMPONENT CONDITION SUMMARY



RECOMMENDATION

This is a baseline read-out on the submitted sample. (Customer Sample Comment: IND2-ICP KV AN KF

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL				
Particles >4µm	ASTM D7647	>5000	<u> </u>				
Particles >6µm	ASTM D7647	>1300	<u> </u>				
Oil Cleanliness	ISO 4406 (c)	>19/17/14	22/18/12				

Customer Id: CHECOB Sample No.: E30000191 Lab Number: 02576360 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Tatiana Sorkina +1 (800)263-3939 tsorkina@e360s.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

GFL 122 Arrow Road - C13100

AG173

Component

Hydraulic System

NOT GIVEN (--- GAL)

Sample Rating Trend ISO

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample. (Customer Sample Comment: IND2-ICP KV AN KF)

Wear

{not applicable}

Contamination

Particles >4µm and oil cleanliness are abnormally high. Particles >6µm are notably high.


Fluid Condition

{not applicable}

				Aug2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		E30000191		
Sample Date		Client Info		03 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185(m)	>20	3		
Chromium	ppm	ASTM D5185(m)	>20	<1		
Vickel	ppm	ASTM D5185(m)	>20	0		
Γitanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	3		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		<1		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		2		
Calcium	ppm	ASTM D5185(m)		49		
Phosphorus	ppm	ASTM D5185(m)		347		
Zinc	ppm	ASTM D5185(m)		397		
Sulfur	ppm	ASTM D5185(m)		777		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<1		
Sodium	ppm	ASTM D5185(m)		1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
Water	%	ASTM D6304*	>0.05	0.002		
ppm Water	ppm	ASTM D6304*	>500	19.2		
FLUID CLEANLI	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u>^</u> 20095		
Particles >6µm		ASTM D7647	>1300	<u>^</u> 2162		
Particles >14µm		ASTM D7647	>160	27		
Particles >21μm		ASTM D7647	>40	5		
Particles >38μm		ASTM D7647	>10	1		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	22/18/12		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: E30000191

Received : 02576360

: 16 Aug 2023 Diagnosed : 22 Aug 2023 Diagnostician : Tatiana Sorkina

: 5629420 Test Package : IND 2 (Additional Tests: KF, KV100, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Environmental 360 Solutions Ltd.

640 Victoria Street Cobourg, ON **CA K9A 5H5** Contact: Fred Kosseim fkosseim@e360s.ca

T: (905)372-2251 F: (905)372-1658