

PROBLEM SUMMARY

Sample Rating Trend DIRT


BOMBARDIER C-FLKY

Component

1 Hydraulic System

SKYDROL LD-4 (2 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Silicon	ppm	ASTM D5185(m)	>15	4 33				

Customer Id: NOV2450MIS Sample No.: WC0696356 Lab Number: 02578577 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com


To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Resample			?	We recommend an early resample to monitor this condition.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



DIRT



BOMBARDIER C-FLKY

Component

1 Hydraulic System

SKYDROL LD-4 (2 LTR)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. We recommend an early resample to monitor this condition.

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material, dirt or grease. The water content is negligible.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

						•
				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0696356		
Sample Date		Client Info		24 Aug 2023		
Machine Age	hrs	Client Info		245		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	1		
Chromium	ppm	ASTM D5185(m)	>10	0		
Nickel	ppm	ASTM D5185(m)	>10	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>10	<1		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	1		
Tin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	1		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	0	0		
Calcium	ppm	ASTM D5185(m)	0	1		
Phosphorus	ppm	ASTM D5185(m)	20000	28680		
Zinc	ppm	ASTM D5185(m)	0	2		
Sulfur	ppm	ASTM D5185(m)	1900	1600		
Lithium	ppm	ASTM D5185(m)		1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	△ 33		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	17		
Water	%	ASTM D6304*	>0.6	0.167		
ppm Water	ppm	ASTM D6304*	>6000	1673.5		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles 5-15μm	count	NAS 1638	>128000	6379		
Particles 15-25µm	count	NAS 1638	>22800	171		
Particles 25-50µm	count	NAS 1638	>4050	182		
Particles 50-100µm	count	NAS 1638	>720	10		
Particles >100μm	count	NAS 1638	>128	81		
NAS 1638	Class	NAS 1638	>9	9		



OIL ANALYSIS REPORT



To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

mattipollari@novajet.ca T: (905)673-0287

F: (905)673-5039