


PLANT 1

PROBLEM SUMMARY


BAY 4 PACKAGING LINE

Main Hydraulic System

COMMERCIAL OIL LUBRIKO AW 46 (500 LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	NORMAL	ATTENTION				
Particles >4µm	ASTM D7647	>5000	10466	3924	<u></u> 5547				
Oil Cleanliness	ISO 4406 (c)	>19/17/14	21/17/12	19/16/10	20/16/11				

Customer Id: TAYSTO Sample No.: WC0754645 Lab Number: 02590030 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Resample			?	We recommend an early resample to monitor this condition.
Information Required			?	Please specify the component make and model with your next sample.

HISTORICAL DIAGNOSIS

29 Jul 2022 Diag: Wes Davis





Resample at the next service interval to monitor. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.



ISO



28 Dec 2020 Diag: Wes Davis

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We recommend you service the filters on this component. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

PLANT 1 **BAY 4 PACKAGING LINE**

Main Hydraulic System

COMMERCIAL OIL LUBRIKO AW 46 (500 LTR)



DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

TR)		De	2020	Jui2022 Oct20	23	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0754645	WC101247	WC
Sample Date		Client Info		01 Oct 2023	29 Jul 2022	28 Dec 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	N/A	N/A
Sample Status				ABNORMAL	NORMAL	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	3	3	3
Chromium	ppm	ASTM D5185(m)	>10	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>10	<1	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	<1
Aluminum	ppm	ASTM D5185(m)	>10	0	0	<1
Lead	ppm	ASTM D5185(m)	>10	<1	<1	2
Copper	ppm	ASTM D5185(m)	>75	6	7	6
Tin	ppm	ASTM D5185(m)	>10	0	<1	<1
Antimony	ppm	ASTM D5185(m)		0	1	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	0	<1
Barium	ppm	ASTM D5185(m)		15	19	18
Molybdenum	ppm	ASTM D5185(m)		0	0	<1
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)		3	3	3
Calcium	ppm	ASTM D5185(m)		107	120	115
Phosphorus	ppm	ASTM D5185(m)		339	381	348
Zinc	ppm	ASTM D5185(m)		421	438	453
Sulfur	ppm	ASTM D5185(m)		2282	2575	2611
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	8	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	<1	<1	<1
Sodium	ppm	ASTM D5185(m)		1	1	2
Potassium	ppm	ASTM D5185(m)	>20	2	<1	<1
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	10466	3924	<u></u> 5547
Particles >6µm		ASTM D7647	>1300	712	424	350
Particles >14µm		ASTM D7647	>160	35	6	11
Particles >21µm		ASTM D7647	>40	9	2	3
Particles >38μm		ASTM D7647	>10	0	0	0
Particles >71μm		ASTM D7647		0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u> </u>	19/16/10	<u>\</u> 20/16/11
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
A -1-I NII (AAI)	1/0111	4 OTM DOT #				0.40

Acid Number (AN)

mg KOH/g ASTM D974*


0.41

0.49

Submitted By: Matthew Fischer



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0754645 : 02590030

Received Diagnosed : 5659096 Diagnostician : 18 Oct 2023

: 19 Oct 2023

: Wes Davis

Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

TAYLOR STEEL 484 ARVIN AVE STONEY CREEK, ON CA L8E 2M9

Contact: George Campanaro gcampanaro@taylorsteel.com

T: (905)662-4925 F: (905)662-4928