

### **PROBLEM SUMMARY**

### Sample Rating Trend


### VISCOSITY

# GENERAL ELECTRIC LLP#8 MOTOR (S/N 266903)

**Bottom Bearing** 

PETRO CANADA TURBOFLO R&O 32 (--- GAL)

### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC 1	TEST RI	ESULTS				
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
Visc @ 40°C	cSt	ASTM D7279(m)	32.0	A 43.1	A 72 7	A 73 0

Customer Id: ONT118MIS **Sample No.:** WC0862782 Lab Number: 02590040 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

### **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

### HISTORICAL DIAGNOSIS

07 Dec 2021 Diag: Kevin Marson

#### VISCOSITY



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



### 15 Apr 2021 Diag: Kevin Marson

#### VISCOSITY



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





### **OIL ANALYSIS REPORT**

SAMPLE INFORMATI

### Sample Rating Trend

### VISCOSITY



history2

## GENERAL ELECTRIC LLP#8 MOTOR (S/N 266903)

Component

**Bottom Bearing** 

PETRO CANADA TURBOFLO R&O 32 (--- GAL)

### DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

### Wear

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the

### Fluid Condition


Viscosity of sample indicates oil is within ISO 46 range, advise investigate. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

ION	method	limit/ba	se (	current	hi
	Apı	2021	Dec2021	0et2023	
,					
)3)					

Sample Number		Client Info		WC0862782	WC0647441	WC0576425
Sample Date		Client Info		05 Oct 2023	07 Dec 2021	15 Apr 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	Not Changd
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>20	<1	<1	1
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	<1	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	<1
Aluminum	ppm	ASTM D5185(m)	>20	0	0	<1
Lead	ppm	ASTM D5185(m)	>20	2	2	1
Copper	ppm	ASTM D5185(m)	>20	1	<1	<1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		0	<1	<1
Barium	ppm	ASTM D5185(m)		<1	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		0	0	0
Calcium	ppm	ASTM D5185(m)	0	3	<1	<1
Phosphorus	ppm	ASTM D5185(m)	4	8	4	4
Zinc	ppm	ASTM D5185(m)	0	7	3	2
Sulfur	ppm	ASTM D5185(m)		144	121	137
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	7	4	2
Sodium	ppm	ASTM D5185(m)		0	0	<1
Potassium	ppm	ASTM D5185(m)	>20	0	<1	<1
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)						0.10



### **OIL ANALYSIS REPORT**







Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: 5659106

₹ 40

20

: WC0862782

Received : 02590040

: 18 Oct 2023 Diagnosed : 19 Oct 2023 Diagnostician : Kevin Marson 40

(B 0.20 0.15

0.00 G

Acid Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 ONTARIO CLEAN WATER AGENCY 1180 LAKESHORE RD. W, SOUTH PEEL FACILITIES - LORNE PARK

MISSISSAUGA, ON **CA L5E 1W6** Contact: Radu Silaghi

Test Package : IND 2 (Additional Tests: TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Viscosity @ 40°C

rsilaghi@ocwa.com

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T:

F: