


# **PROBLEM SUMMARY**

#### Area [412632107] Machine Id 1000029391 CHAIN HOOKS TRIPE Component

Gearbox

#### Fluid KLUBER KLUBEROIL 4 UH1-460 N (--- GAL)

# COMPONENT CONDITION SUMMARY



# RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	ABNORMAL	NORMAL		
Lithium	ppm	ASTM D5185(m)		<mark>/</mark> 37	<b>A</b> 31	3	


### Customer Id: CARGUE Sample No.: WC0848517 Lab Number: 02591416 Test Package: IND 2



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Kevin Marson +1 (289)291-4644 x4644 <u>Kevin.Marson@wearcheck.com</u>

*To change component or sample information:* Gloria Gonzalez +1 (289)291-4643 x4643 <u>gloria.gonzalez@wearcheck.com</u>



RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.			
Resample			?	We recommend an early resample to monitor this condition.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.			

# HISTORICAL DIAGNOSIS

#### 17 Jul 2023 Diag: Kevin Marson



We advise that you check all areas where contaminants can enter the system. We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for topup/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Lithium (Li) level abnormal, indicates possible grease contamination. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.



view report



#### 20 Apr 2023 Diag: Wes Davis

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

#### NORMAL



# 20 Jan 2023 Diag: Wes Davis

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

# Area [412632107] 1000029391 CHAIN HOOKS TRIPE Component

Gearbox Fluic

KLUBER KLUBEROIL 4 UH1-460 N (--- GAL)

# DIAGNOSIS

# Recommendation

We advise that you check all areas where contaminants can enter the system. We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

# Wear


All component wear rates are normal.

#### Contamination

Lithium (Li) level abnormal 37ppm., indicates possible grease contamination.

#### Fluid Condition


Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.





SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0848517	WC0835769	WC0811997
Sample Date		Client Info		18 Oct 2023	17 Jul 2023	20 Apr 2023
Machine Age	days	Client Info		0	0	0
Oil Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		10	10	0
Iron	ppm	ASTM D5185(m)	>200	18	15	1
Chromium	ppm	ASTM D5185(m)	>15	0	0	0
Nickel	ppm	ASTM D5185(m)	>15	0	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	0
Aluminum	ppm	ASTM D5185(m)	>25	0	<1	0
Lead	ppm	ASTM D5185(m)	>100	<1	0	0
Copper	ppm	ASTM D5185(m)	>200	6	3	1
Tin	ppm	ASTM D5185(m)	>25	0	0	<1
Antimony	ppm	ASTM D5185(m)	>5	0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		15	13	6
Barium	ppm	ASTM D5185(m)		2	2	0
Molybdenum	ppm	ASTM D5185(m)		9	9	4
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		0	<1	0
Calcium	ppm	ASTM D5185(m)		38	38	3
Phosphorus	ppm	ASTM D5185(m)		611	679	571
Zinc	ppm	ASTM D5185(m)		19	19	2
Sulfur	ppm	ASTM D5185(m)		796	766	743
Lithium	ppm	ASTM D5185(m)		<mark>/</mark> 37	<b>A</b> 31	3
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	19	22	8
Sodium	ppm	ASTM D5185(m)		<1	<1	0
Potassium	ppm	ASTM D5185(m)	>20	17	15	3
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.61	0.53	0.60




# **OIL ANALYSIS REPORT**











VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	VLITE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	VLITE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	460	426	419	409
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color					- Statuter	
Bottom						





Feb7/20 Jov5/20

Aug 14/18

Aav9/19

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 **Cargill Meat Solutions** CALA Sample No. : WC0848517 Received : 24 Oct 2023 165 Dunlop Drive Lab Number : 02591416 Diagnosed : 25 Oct 2023 Guelph, ON ISO 17025:2017 Accredited Laboratory Unique Number : 5668495 Diagnostician : Kevin Marson CA N1L 1P4 Test Package : IND 2 (Additional Tests: TAN Man) Contact: Jakub Posluszny To discuss this sample report, contact Customer Service at 1-800-268-2131. jakub\_posluszny@cargill.com Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (519)823-5200 Validity of results and interpretation are based on the sample and information as supplied. F: (519)823-5893

Contact/Location: Jakub Posluszny - CARGUE

pr20/23