

# **PROBLEM SUMMARY**

# Sample Rating Trend

ISO


# BUILDING 51 - CEREAL PRODUCTS Machine Id ROTARY FEEDER PRODUCT GEAR BOX (S/N 51RFPR-GB)

Component

Gearbox

**LUBRICATION ENG DUOLEC 1605 GEAR OIL 220 (--- LTR)** 

## **COMPONENT CONDITION SUMMARY**



#### RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST	RESULTS			
Sample Status			SEVERE	 
Particles >4µm	ASTM D7647	>20000	<b>128473</b>	 
Particles >6µm	ASTM D7647	>5000	<b>40908</b>	 
Particles >14μm	ASTM D7647	>640	<b>△</b> 3188	 
Particles >21μm	ASTM D7647	>160	<b>A</b> 894	 
Particles >38μm	ASTM D7647	>40	<u></u> 91	 
Oil Cleanliness	ISO 4406 (c)	>21/19/16	24/23/19	 

Customer Id: HIRWIN Sample No.: WC0865419 Lab Number: 02601340 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.			

# HISTORICAL DIAGNOSIS




# **OIL ANALYSIS REPORT**

**BUILDING 51 - CEREAL PRODUCTS** ROTARY FEEDER PRODUCT GEAR BOX (S/N 51RFPR-GB)

Component

Gearbox

**LUBRICATION ENG DUOLEC 1605 GEAR OIL 220 (--- LTR)** 





DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

#### Wear

All component wear rates are normal.

## Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.


### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

IL 220 ( LTR)				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0865419		
Sample Date		Client Info		01 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	77		
Chromium	ppm	ASTM D5185(m)	>15	<1		
Nickel	ppm	ASTM D5185(m)	>15	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>100	0		
Copper	ppm	ASTM D5185(m)	>200	<1		
Tin	ppm	ASTM D5185(m)	>25	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		37		
	ppiii	( )		• •		
Barium	ppm	ASTM D5185(m)		2		
Barium Molybdenum		. ,				
	ppm	ASTM D5185(m)		2		
Molybdenum	ppm ppm	ASTM D5185(m) ASTM D5185(m)		2		
Molybdenum Manganese	ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		2 0 <1		
Molybdenum Manganese Magnesium	ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		2 0 <1 <1		
Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		2 0 <1 <1 8		
Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		2 0 <1 <1 8 688		
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm	ASTM D5185(m)		2 0 <1 <1 8 688 20		
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base	2 0 <1 <1 8 688 20 8532		
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	limit/base >50	2 0 <1 <1 8 688 20 8532 <1		
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)		2 0 <1 <1 8 688 20 8532 <1	   history1	    history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINANTS	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)		2 0 <1 <1 8 688 20 8532 <1 current	   history1	    history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINANTS Silicon Sodium	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  method  ASTM D5185(m) ASTM D5185(m)	>50	2 0 <1 <1 8 688 20 8532 <1 current		
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINANTS Silicon Sodium Potassium	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	>50 >20	2 0 <1 <1 8 688 20 8532 <1 current <1 2	history1	history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINANTS Silicon Sodium Potassium  FLUID CLEANLIN	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)	>50 >20 limit/base	2 0 <1 <1 8 688 20 8532 <1 current <1 2 1	history1	history2 history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINANTS Silicon Sodium Potassium FLUID CLEANLIN Particles >4µm Particles >6µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m)  ASTM D5185(m)  ASTM D5185(m)  ASTM D5185(m)  ASTM D5185(m)  ASTM D5185(m)	>50 >20 limit/base >20000	2 0 <1 <1 8 688 20 8532 <1 current <1 2 1 current  128473	history1 history1	history2 history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINANTS Silicon Sodium Potassium FLUID CLEANLIN Particles >4µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  MASTM D5185(m)  MASTM D5185(m) ASTM D5185(m)	>50 >20 limit/base >20000 >5000	2 0 <1 <1 8 688 20 8532 <1 current <1 2 1 current △ 128473 ♠ 40908	history1 history1	history2 history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINANTS Silicon Sodium Potassium FLUID CLEANLIN Particles >4µm Particles >14µm Particles >14µm Particles >21µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  METHOD  METHOD  ASTM D5185(m) ASTM D7647 ASTM D7647	>50 >20 limit/base >20000 >5000 >640	2 0 <1 <1 8 688 20 8532 <1 current <1 2 1 current  41 24 40908 3188		history2 history2
Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium  CONTAMINANTS Silicon Sodium Potassium Ptuld CLEANLIN Particles >4µm Particles >6µm Particles >14µm	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185(m)  METHOD  ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D7647 ASTM D7647 ASTM D7647	>50 >20 limit/base >20000 >5000 >640 >160	2 0 <1 <1 8 688 20 8532 <1 current <1 2 1 current  ^ 128473	history1 history1	history2 history2



# OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WC0865419 : 02601340 : 5694425

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received

: 06 Dec 2023 : 07 Dec 2023 Diagnosed : Wes Davis Diagnostician Test Package : IND 2 (Additional Tests: TAN Man)

HIRAM WALKER & SONS LTD. 2072 RIVERSIDE DRIVE EAST, BOX 2518 WINDSOR, ON

> CA N8Y 4S5 Contact: Matt Morand matt.morand@pernod-ricard.com

T: (519)561-5359 F: (519)971-5719

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.