

# **PROBLEM SUMMARY**

# PROBLEM SUMMAR


# [1001062752] Machine Id BOEING 737 MAX C-FTXF

Component A Hydraulic System

SKYDROL LD-4 (--- GAL)

# Sample Rating Trend VISCOSITY Dec2023

# COMPONENT CONDITION SUMMARY



## RECOMMENDATION

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL					
Visc @ 40°C	cSt	ASTM D7279(m)	11.42	<b>△</b> 6.6					

Customer Id: SUNETO
Sample No.: WC0881033
Lab Number: 02601743
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED AC	RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.		

# HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

# Area [1001062752] **BOEING 737 MAX C-FTXF**

A Hydraulic System

SKYDROL LD-4 (--- GAL)

# Sample Rating Trend



# **DIAGNOSIS**

### Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

### Wear

All component wear rates are normal.

### Contamination

The water content is negligible. There is no indication of any contamination in the oil. The system and fluid cleanliness is acceptable.


## Fluid Condition

The oil viscosity is lower than typical, possibly indicating the addition of lighter grade oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0881033		
Sample Date		Client Info		06 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	nnm	ASTM D5185(m)	>20	3		
Chromium	ppm	ASTM D5185(m)	>10	ა <1		
Nickel		ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)	>10	0		
Silver	ppm	ASTM D5185(m)		<1		
	ppm	. ,	- 10	<1		
Aluminum	ppm	ASTM D5185(m)	>10	<1 <1		
Lead	ppm	ASTM D5185(m)	>20	<1 7		
Copper	ppm	ASTM D5185(m)	>20			
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		4		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	1		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	0	<1		
Calcium	ppm	ASTM D5185(m)	0	3		
Phosphorus	ppm	ASTM D5185(m)	20000	34653		
Zinc	ppm	ASTM D5185(m)	0	2		
Sulfur	ppm	ASTM D5185(m)	1900	1497		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2		
Sodium	ppm	ASTM D5185(m)		4		
Potassium	ppm	ASTM D5185(m)	>20	21		
Water	%	ASTM D6304*	>0.6	0.222		
ppm Water	ppm	ASTM D6304*	>6000	2230		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles 5-15µm	count	NAS 1638	>128000	10219		
Particles 15-25µm	count	NAS 1638	>22800	906		
Particles 25-50µm	count	NAS 1638	>4050	360		
Particles 50-100µm	count	NAS 1638	>720	73		
Particles >100µm	count	NAS 1638	>128	7		
NAS 1638	Class	NAS 1638	>9	6		



# **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: WC0881033 : 02601743

: 5694828

Received : 07 Dec 2023 : 11 Dec 2023 Diagnosed Diagnostician : Kevin Marson

Test Package : IND 2 ( Additional Tests: KF, PrtCount, TAN Man )

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

**SUNWING AIRLINES** 

44 FASKEN DRIVE, UNIT 12/13 ETOBICOKE, ON CA M9W 5M8

Contact: Geoff Carroll gcarroll@flysunwing.com T: (416)802-9643

F: (416)640-1595