


## **PROBLEM SUMMARY**

5

# 5-3-174 Overburden Belt Conveyor


Component Gearbox


**MOBIL DTE OIL EXTRA HEAVY (20 LTR)** 





#### **COMPONENT CONDITION SUMMARY**





#### RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for topup/fill. Resample at the next service interval to monitor. The fluid was specified as MOBIL DTE OIL EXTRA HEAVY, however, a fluid match indicates that this fluid is ISO 220 Gear Oil. Please confirm the oil type and grade on your next sample.

#### PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
Calcium	ppm	ASTM D5185(m)		<u>4</u>	<u>4</u>	<b>△</b> <1
Zinc	ppm	ASTM D5185(m)		<u>^</u> 2	<b>A</b> 3	<u>^</u> 2
Visc @ 40°C	cSt	ASTM D7279(m)	146	<b>^</b> 215	<u>^</u> 214	<u>^</u> 214

Customer Id: STMBOW **Sample No.:** WC0869861 Lab Number: 02602016 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

#### RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Alert			?	The fluid was specified as MOBIL DTE OIL EXTRA HEAVY, however, a fluid match indicates that this fluid is ISO 220 Gear Oil. Please confirm the oil type and grade on your next sample.
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

#### HISTORICAL DIAGNOSIS

#### 07 Sep 2023 Diag: Bill Quesnel

VISCOSITY



We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. Calcium and/or magnesium levels higher than normal indicating possible contamination with cement dust, advise investigate. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 220 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid.



VISCOSITY



#### 18 May 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as MOBIL DTE OIL EXTRA HEAVY, however, a fluid match indicates that this fluid is ISO 220 Gear Oil. Please confirm the oil type and grade on your next sample. All component wear rates are normal. Calcium and/or magnesium levels higher than normal indicating possible contamination with cement dust, advise investigate. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 220 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid.



VISCOSITY



### 16 Nov 2022 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as MOBIL DTE OIL EXTRA HEAVY, however, a fluid match indicates that this fluid is ISO 220 Gear Oil. Please confirm the oil type and grade on your next sample. All component wear rates are normal. Calcium and/or magnesium levels higher than normal indicating possible contamination with cement dust, advise investigate. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within ISO 220 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid.






**OIL ANALYSIS REPORT** 

# 5-3-174 Overburden Belt Conveyor

Gearbox

**MOBIL DTE OIL EXTRA HEAVY (20 LTR)** 





#### **DIAGNOSIS**

#### Recommendation

We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as MOBIL DTE OIL EXTRA HEAVY, however, a fluid match indicates that this fluid is ISO 220 Gear Oil. Please confirm the oil type and grade on your next sample.

#### Wear

All component wear rates are normal.

#### Contamination

Calcium and/or magnesium levels higher than normal indicating possible contamination with cement dust, advise investigate. There is no indication of any contamination in the oil.


#### Fluid Condition

Viscosity of sample indicates oil is within ISO 220 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0869861	WC0842666	WC0818133
Sample Date		Client Info		23 Nov 2023	07 Sep 2023	18 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>200	11	8	3
Chromium	ppm	ASTM D5185(m)	>15	0	0	0
Nickel	ppm	ASTM D5185(m)	>15	<1	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	0
Aluminum	ppm	ASTM D5185(m)	>25	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>100	0	0	0
Copper	ppm	ASTM D5185(m)	>200	<1	<1	0
Tin	ppm	ASTM D5185(m)	>25	0	0	0
Antimony	ppm	ASTM D5185(m)	>5	0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		9	6	2
Barium	ppm	ASTM D5185(m)		<1	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		0	0	0
Calcium	ppm	ASTM D5185(m)		<u></u> 4	<u>4</u>	<u></u> <1
Phosphorus	ppm	ASTM D5185(m)		284	320	338
Zinc	ppm	ASTM D5185(m)		<u>^</u> 2	<b>A</b> 3	<u>^</u> 2
Sulfur	ppm	ASTM D5185(m)		9096	9264	9401
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	4	4	5
Sodium	ppm	ASTM D5185(m)		<1	<1	0
Potassium	ppm	ASTM D5185(m)	>20	0	0	0
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.49	0.33	0.25



### OIL ANALYSIS REPORT







Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WC0869861

: 5695101

150

100

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 02602016

Diagnosed Diagnostician € 0.72 흔 0.48

₹ 0.24 00.00 PG

May18/23

: 08 Dec 2023

: 11 Dec 2023

: Kevin Marson

Test Package : IND 2 (Additional Tests: TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

ST. MARYS CEMENT CO. 400 BOWMANVILLE AVENUE

BOWMANVILLE, ON **CA L1C 7B5** 

Contact: Lou Traiforos lou.traiforos@vcimentos.com T: (905)440-5874

F: (905)623-4695