

OIL ANALYSIS REPORT

BRUCE B/0B/54300 0B-54300-EPG1-E2

Component

Diesel Engine

SHELL ROTELLA T4 15W40 (30 LTR)





DIAGNOSIS

Recommendation

We advise that you check for the source of the coolant leak. We recommend that you drain the oil from the component if this has not already been done. We advise that you flush the component thoroughly before re-filling with oil. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Test for glycol is positive. There is a light concentration of glycol present in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0677272	WC0677278	WC0677280
Sample Date		Client Info		11 Dec 2023	16 Nov 2023	16 Nov 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	4	3	3
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>2	<1	0	0
Titanium	ppm	ASTM D5185(m)	>2	0	0	0
Silver	ppm	ASTM D5185(m)	>2	<1	<1	<1
Aluminum	ppm	ASTM D5185(m)	>30	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>30	<1	<1	<1
Copper	ppm	ASTM D5185(m)	>30	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>15	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		169	171	171
Barium	ppm	ASTM D5185(m)		<1	<1	<1
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		10	10	12
Calcium	ppm	ASTM D5185(m)		2020	2020	2021
Phosphorus	ppm	ASTM D5185(m)		906	918	918
Zinc	ppm	ASTM D5185(m)		1049	1038	1041
Sulfur	ppm	ASTM D5185(m)		2781	2733	2745
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>30	21	18	16
Sodium	ppm	ASTM D5185(m)		2	2	2
Potassium	ppm	ASTM D5185(m)	>20	<u>^</u> 6	<u>^</u> 6	<u>^</u> 6
Glycol	%	ASTM D7922*		<u> </u>	△ 0.015	△ 0.016
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0	0	0
Nitration	Abs/cm	ASTM D7624*	>20	4.9	4.9	4.9
Sulfation	Abs/.1mm	ASTM D7415*	>30	20.0	20.3	20.2



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0677272 : 02602563

Received Diagnosed : 5695648

Diagnostician Test Package : MOB 2 (Additional Tests: Glycol)

: 12 Dec 2023 : 14 Dec 2023 : Wes Davis

Bruce Power - Bruce A PdM P.O.Box 1540, 177 Tie Road,, RM-222 U2 Column 2N11 615

Tiverton, ON CA NOG 2T0

Contact: Bradley Mangotich bradley.mangotich@brucepower.com T: (519)361-2673

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: